

Confined Space Register

Hazard ID	Building No. Floor Level Room No.	Campus Code Location	Description	Sample No.	Partially Enclosed or Enclosed	Likely to be Entered	Oxygen Concentration	Airborne Impairment	Airborne Injury	Free Flowing Solid or Liquid	RA Required	Risk Management Action	Labelled y/n	Comments
					A	B	C	D	E	F				

Applied Science

38934	311 Ground External	Bentley External - Experimental Courtyard	Confined Space Detected	Visual	Yes	Yes	No	Yes	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	No	REMOVED
38935	311 Ground External	Bentley External - Experimental Courtyard	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Three concrete tanks set into brick courtyard. Possibly used for aqua culture research. Tanks are approx. 1 meter diameter by 2 meters deep, approximately 1 meter of water. Tanks are labelled with "Confined Space" danger signs and covered with metal mesh covers. Note: Mesh cover material is corroded and is not sufficient or rated as material for load bearing pit cover.	Yes	REMOVED

Architecture & Design

38923	201 Level 1 102a	Bentley Room 102a - Open Pit	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	Yes	Potentially energized equipment located in space.
--------------	-------------------------------	------------------------------------	----------------------------	--------	-----	-----	----	----	----	-----	------------	--	-----	---

Art / Jewellery Block

38952	202 Ground	Bentley Hopper - North East of B202	Confined Space - To be inspected	Visual	Yes	Yes	No	Yes	No	No	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk		To be inspected at the next confined Space survey.
--------------	----------------------	---	-------------------------------------	--------	-----	-----	----	-----	----	----	------------	--	--	--

Brodie Hall

38930	610 Ground External	Bentley External - East side grounds	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk.	No	
--------------	----------------------------------	--	----------------------------	--------	-----	-----	----	----	----	-----	------------	---	----	--

Confined Space Register

Hazard ID	Building No.		Description	Sample No.	Partially Enclosed or Enclosed	Likely to be Entered	Oxygen Concentration	Airborne Impairment	Airborne Injury	Free Flowing Solid or Liquid	RA Required	Risk Management Action	Labelled y/n	Comments
	Floor Level	Campus Code Location												
	Room No.	Location			A	B	C	D	E	F				

Building Office Compound

38924	110 Ground External	Bentley Hopper - Southwest Corner	Confined Space Detected	Visual	Yes	Yes	No	Yes	Yes	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	Yes	Entry is unlikely Dust collection systems are designed to be maintained and repaired without entry. Most of the space in this equipment is filled with filters, motors, fans, etc that are accessed by outside the equipment.
--------------	----------------------------------	---	----------------------------	--------	-----	-----	----	-----	-----	-----	------------	--	-----	---

Car Park

38962	D3 Car Ground External	Bentley Car Park	Confined Space Suspected	Visual	Yes	Yes	No	No	No	Yes	Yes	To be inspected at next survey for confirmation	No	Tank access point is locked
--------------	-------------------------------------	---------------------	-----------------------------	--------	-----	-----	----	----	----	-----	------------	---	----	-----------------------------

Central Plant

38921	117 Ground External	Bentley Ground Floor - Gas powered boilers	No Confined Space Detected	Visual	Yes	No	No	No	No	No	No	Space is not classified as a Confined Space, but controls are required for maintenance and repair activities. Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	No	The space cannot be entered
38922	117 Ground External	Bentley Ground - Water Chillers	No Confined Space Detected	Visual	Yes	No	No	No	No	No	No	Space is not classified as a Confined Space, but controls are required for maintenance and repair activities. Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	No	The space is not entered

Chemical Store

38940	707 Ground External	kalgoorlie South East of Building	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	Yes	Top sealed across hatches
--------------	----------------------------------	---	----------------------------	--------	-----	-----	----	----	----	-----	------------	--	-----	---------------------------

Confined Space Register

Hazard ID	Building No. Floor Level Room No.	Campus Code Location	Description	Sample No.	Partially Enclosed or Enclosed or Likely to be Entered A	Oxygen Concentration B	Airborne Impairment C	Airborne Injury D	Free Flowing Solid or Liquid E	RA Required F	Risk Management Action	Labelled y/n	Comments
-----------	---	-------------------------	-------------	------------	--	----------------------------------	---------------------------------	-----------------------------	--	-------------------------	------------------------	--------------	----------

Chemistry

38931	500 Ground External	Bentley External - South of Building	Confined Space Detected	Visual	Yes	Yes	No	Yes	Yes	Yes	Yes	No	Entry is unlikely. Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk Entry is unlikely. Dust collection systems are designed to be maintained and repaired without entry. Most of the space in this equipment is filled with filters, motors, fans, etc that are accessed by outside the equipment.
--------------	----------------------------------	---	-------------------------	--------	-----	-----	----	-----	-----	-----	-----	----	---

Chiller Water Tank

39107	Chiller Ground	Bentley Campus North	5 Million Litre tank		Yes	Yes	No	No	No	Yes	Yes	No	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk To be inspected at the next confined Space survey.
--------------	--------------------------	-------------------------	----------------------	--	-----	-----	----	----	----	-----	-----	----	--

Curtin Business School One

38919	402 Ground 106	Bentley Room 106 (Plant Room) - Door located on building exterior.	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	No	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk Space contains water pump and pipes.
38920	402 Roof External	Bentley Roof - Water Tank	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	No	Not likely to be entered, fall hazard associated with accessing cover is controlled with tie-off points and procedures. Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk Diesel powered pumps exhaust to atmosphere outside the room.

Field trials area

38960	126 Ground External	Bentley External - 1000Ltr Tank	Confined Space Suspected	Visual	Yes	Yes	No	No	No	Yes	Yes	No	To be inspected at next survey for confirmation Tank access point is locked
--------------	----------------------------------	------------------------------------	--------------------------	--------	-----	-----	----	----	----	-----	-----	----	--

Confined Space Register

Hazard ID	Building No.		Description	Sample No.	Partially Enclosed or Enclosed	Likely to be Entered	Oxygen Concentration	Airborne Impairment	Airborne Injury	Free Flowing Solid or Liquid	RA Required	Risk Management Action	Labelled y/n	Comments
	Floor Level	Campus Code Location												
	Room No.	Location			A	B	C	D	E	F				

Fuels & Energy Research Facility

38927	611 Ground External	Bentley External - East Exterior	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	Yes	
38928	611 Ground External	Bentley External - East Exterior	Confined Space Detected	Visual	Yes	Yes	No	No	No	Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk.	Yes	
38929	611 Ground External	Bentley External - North Exterior Side	Confined Space Detected	Visual	Yes	Yes				Yes	Yes	Manage by documented routine processes and procedures, monitor periodically to determine situation changes which may affect the risk	No	

Hayman Road end of Campus

38961	North Ground External	Bentley External	Confined Space Suspected	Visual	Yes	Yes	No	No	No	Yes	Yes	To be inspected at next survey for confirmation	No	Tank access point is locked
--------------	---------------------------------	---------------------	--------------------------	--------	-----	-----	----	----	----	-----	------------	---	----	-----------------------------

John Curtin Building

38949	200A Loading	Bentley Loading Dock	Confined Space - To be inspected								Yes	If required to be entered prior to the next survey, a risk assessment is required. Refer to AS2865.	No	Unable to access space. Inspect at next survey.
--------------	------------------------	-------------------------	----------------------------------	--	--	--	--	--	--	--	------------	---	----	---

Ken Hall Lecture Theatre

38948	403 Ceiling	Bentley Ceiling Space	Confined Space - To be Inspected								Yes	If required to be entered prior to the next survey, a risk assessment is required. Refer to AS2865.	No	Unable to access space. Inspect at next survey.
--------------	-----------------------	--------------------------	----------------------------------	--	--	--	--	--	--	--	------------	---	----	---

Confined Space Register

Hazard ID	Building No.		Description	Sample No.	A	B	C	D	E	F	RA Required	Risk Management Action	Labelled y/n	Comments
	Floor Level	Campus Code												
	Room No.	Location												

Confined Space Definitions

- A - Is the space enclosed or partially enclosed?
- B - Is it likely to be entered?
- C - Has space an oxygen concentration outside the safe oxygen range?
- D - Has space an airborne contaminant that may cause impairment, loss of consciousness or asphyxiation?
- E - Has space an airborne contaminant that may cause injury from a fire or explosion?
- F - Has space a stored free flowing solid or a rising level of liquid that may cause suffocation or drowning by engulfment?